



Checklist of Recalled Toys and Children's Products

CONSUMER INFORMATION SHEET

Make sure these toys are not on your holiday gift list.

- **Bumble Bee Toys** (398,000) distributed by Graco Children's Products. Graco received 26 reports of the antennae breaking off the bumble bee toys, including five reports of children who started to choke on the broken antennae. One child's throat was scratched when the child's mother removed the broken antenna from the child's mouth. Call Graco at (800) 258-3213 to receive a free replacement toy.
- **Nerf® Big Play Football** (294,000) distributed by Hasbro. The football contains a hard plastic interior frame that can pose a risk of facial cuts if a child is hit during play. There have been nine reports of facial injuries, including eight requiring stitches or medical attention. Call Hasbro at (866) 637-3244 or visit the firm's Web site at www.hasbro.com/nerf to receive a replacement NERF product of equal value.
- **Carter's Children's Mirror Books** (225,000) distributed by Kids II Inc. The mirror in the books can crack or break, posing a laceration hazard to young children. Kids II has received 26 reports of the mirror cracking or breaking, including four reports of cuts and one report of a pinched finger. Call Kids II at (877) 325-7056 or visit the firm's Web site at www.kidsii.com for instructions on returning the mirror for a refund.
- **Radio-Control Toy Trucks** (287,000) distributed by Nikko America Inc. A problem with the circuit board causes the toy truck to overheat, posing a fire and burn hazard. No injuries have been reported. Call Nikko America at (866) 232-6013 for instructions on returning the product for a free circuit board replacement.
- **Ride-On Toys** (70,000) distributed by Tek Nek Toys International. The screw and nut assembly attaching the steering wheel can come loose, posing a choking and aspiration hazard to young children. Tek Nek Toys has received six reports of the screw and nut coming loose, including the death of an 18-month-old boy who aspirated a screw. Call Tek Nek Toys at (888) 661-0222 to receive free replacement parts.

(more)

- **BATMAN™ BATMOBILE™ Toy Vehicle** (314,000) distributed by Mattel Inc. The rear tail wings of the Batmobile are made of rigid plastic and come to a point, which poses a potential puncture or laceration hazard to young children. Mattel has received 14 reports of injuries consisting of scrapes, scratches, lacerations and punctures. Four of the injuries required medical treatment. Call Mattel at (888) 271-9891 to determine if the toy is among the recalled models and to order the free replacement wings if needed.
- **Children’s Athletic Shoes** (441,000) distributed by Payless ShoeSource Inc. The metal eyelet lace holder at the top of the shoes can detach, posing a choking hazard to young children. Payless ShoeSource has received one report of a child starting to choke on a detached eyelet from one of these shoes. No injuries have been reported. Call Payless at (800) 654-697 or visit the firm’s Web site at www.payless.com for information on returning these shoes to a Payless ShoeSource store for a cash refund or exchange.
- **“Rock ‘N Roller” Baby Strollers** (300,000) distributed by Dorel Juvenile Group USA. If the stop pins are bent or missing or the seat is not fully attached, the seat can partially detach from the frame during use and the infant occupant can be injured in a fall. There have been 77 reports of problems related to the stroller seats. Injuries included one child who fell and had a slight concussion and another child who cut his forehead and required stitches. Additionally, there were 46 reports of bumps and bruises. Call Dorel Juvenile Group at (800) 711-0402 to determine how to inspect the stroller for possible replacement.
- **Metal Toy Jewelry Sold in Vending Machines** (150 million pieces) by four toy jewelry importers (AA Global Industries Inc., Brand Imports, Cardinal Distributing Co. and L.M. Becker & Co. Inc.). Some of the toy jewelry contains dangerous levels of lead. CPSC has received one report of lead poisoning when a child swallowed a piece of toy jewelry containing lead that was previously recalled. No reports of injuries or illnesses have been received from products by these companies listed above. Consumers should throw away recalled jewelry. Call Toy Jewelry Recall Hotline for more information at (800) 441-4234.
- **Toddler’s Athletic Shoes** (140,000) distributed by Reebok International. The I-3 logo-tag on the tongue of the shoe can be peeled off, posing a choking hazard to young children. Reebok has received a report of an 8-month-old child mouthing the logo-tag. The tag was removed without injury. Call Reebok at (800) 843-4444 or visit the firm’s Web site at www.reebok.com to receive a refund.

--more--

The Following Safety Tips Will Also Help In Choosing Appropriate Toys

- Select toys to suit the age, abilities, skills and interest level of the intended child. Toys too advanced may be hazardous for younger children.
- Infants, toddlers and children like to put objects in their mouths, so avoid toys with small parts, which could be a fatal choking hazard.
- Look for sturdy construction, like tightly secured eyes, noses and other potential small parts.
- Avoid toys that have sharp edges and points for all children under 8.
- Do not purchase electric toys with heating elements for children under 8.
- Be a label reader. Look for toy labels that give age and safety recommendations and use that information as a guide.
- Check toy instructions for clarity – for both you and the child.

Immediately discard plastic wrappings on toys, which can cause suffocation, before they become deadly playthings.

###
